

How to reduce downtimes. **And follow-up costs.**

A functioning forklift truck is a vital part of your material flow. These four efficiency tips will keep it running.

1. Optimisation of operational processes.

Regularly analyse your operational processes to identify and eliminate inefficiencies. All Jungheinrich electric forklift trucks are equipped with a telematics box, providing the possibility for comprehensive data analysis in your warehouse.

2. Preventive maintenance.

Establish a preventive maintenance strategy that features regular check-ups and servicing for your forklifts. By providing first-class service and support for all of your trucks, we ensure maximum planning security. Our individually tailored services will help your company advance in warehouse logistics.

3. Spare parts management with a reliable partner.

Ensure quick access to critical spare parts by partnering with a reliable supplier. This reliable partnership ensures that necessary parts are available quickly and consistently, keeping your operations running smoothly without interruption.

4. Investment in modern technologies.

Invest in advanced technologies such as assistance systems, predictive maintenance or fleet management systems to improve the performance and reliability of your forklifts. These technologies help you identify potential issues early and address them proactively, thereby reducing downtime and follow-up costs.

Time is money. Invest some in knowledge.

Discover more about our Service Solutions [here](#).

JUNGHEINRICH

Keep your business running:
a well-maintained forklift truck keeps your material flow going.

Consistent productivity.

Predictable handling times.



Enhanced safety.

Consistent operational efficiency.